



## Update status 1631A-400S

Date 18/05/2018

Earlier this year you have been informed that the 1631-16S Defluxer & Maintenance Cleaner will be reformulated because of the HFC regulations. The initial stock is set to arrive and we wanted to remind you what the changes are.

### What is changing:

- 1631-16S will be replaced by 1631A-16S.
- The current HFC-134a propellant will be replaced with HFO-1234ze.
- **1631A-16S will no longer include a brush which could be attached to the accusol, but will have a spray head.**



**1631-16S**  
Current Bottle



**1631A-16S**  
New Bottle



**New 1631A-16S Spray head**

To ensure that the G3 Defluxer remains non-flammable, the brush head had to be replaced with a spray head. This change does not effect the product performance of the new 1631A-16S.

To accommodate you with these changes the new TDS and SDS have been linked in this e-mail:

- [TDS 1631A-16S](#)
- [SDS 1631A-16S](#)

There are no price changes for 1631A-16S. If any other changes will be implemented, we will make sure to update you as soon as possible. In case of questions, please contact your Regional Sales Manager or designated sales support employee.

Kind regards,  
ITW Contamination Control



**TECHSPRAY™**